

POINT NUMBER	ADDRESS	STREET TREE	PROBLEM	NUMBER OF PANELS
1	3305 BARRINGTON DR	YES	CRACK IN SIDEWALK FROM TREE TO YARD	3
2	3305 BARRINGTON DR	YES	UPHEAVAL AT TREE	2
3	3383 BARRINGTON DR	YES	UPHEAVAL CAUSED BY STREET TREE	4
4	3383 BARRINGTON DR	YES	UPHEAVAL CAUSED BY STREET TREE	3
5	3411 BARRINGTON DR	YES	MULTIPLE UPHEAVALS	4
6	3417 BARRINGTON DR	YES	UPHEAVAL AT DRIVEWAY RAMP NEAR TREE	2
7	3457 BARRINGTON DR	YES	TWO UPHEAVAL AND ONE SUNKEN PORTION OF SIDEWALK	3
8	2793 BEACON HILL DR	YES	LOCATION ON BARRINGTON UPHEAVAL ON STREET SIDE	3
9	2790 BEACON HILL DR	NO	AT NORTH PROPERTY LINE UPHEAVAL CAUSE UNKNOWN	2
10	2790 BEACON HILL DR	YES	UPHEAVAL NEAR TREE	4
11	2810 BEACON HILL DR	YES	UPHEAVAL AT DRIVEWAY RAMP	2
12	2810 BEACON HILL DR	YES	UPHEAVAL SOUTH OF DRIVEWAY RAMP	2
13	2812 BEACON HILL DR	NO	25 FEET OF SIDEWALK RAISED BY ROOTS FROM A COTTONWOOD TREE ON LOT	5
14	3802 WELLINGTON CT	YES	UPHEAVAL	4
15	2030 WELLINGTON DR	YES	TREE REMOVED HUGE BUCKLE IN SIDEWALK STORMWATER PROBLEM AT BUCKLE	3
16	3802 WELLINGTON CT	YES	UPHEAVAL	3
17	3832 WELLINGTON CT	YES	LARGE UPHEAVAL AT DRIVEWAY RAMP	2
18	3842 WELLINGTON CT	YES	CRACK AND UPHEAVAL	2
19	3862 WELLINGTON CT	YES	UPHEAVAL AT DRIVEWAY RAMP	2
20	3863 WELLINGTON CT	YES	3" UPHEAVAL AT ELECTRICAL BOX NEAR TREE	3
21	3853 WELLINGTON CT	YES	UPHEAVAL ON STREET SIDE	2
22	2057 WELLINGTON DR	YES	2" UPHEAVAL	2
23	2057 WELLINGTON DR	YES	1" UPHEAVAL	2
24	2067 WELLINGTON DR	YES	MINOR UPHEAVAL	1
25	2073 WELLINGTON DR	YES	UPHEAVAL HIGHER ON STREET SIDE	3
26	2095 WELLINGTON DR	YES	UPHEAVAL AT DRIVEWAY RAMP	2
27	2097 WELLINGTON DR	YES	UPHEAVAL THAT RUNS FROM STREET LIGHT AND TREE	2
28	2097 WELLINGTON DR	YES	1" UPHEAVAL	3
29	2109 WELLINGTON DR	YES	UPHEAVAL NEAR WATER METERS	2
30	2109 WELLINGTON DR	YES	UPHEAVAL AT DRIVEWAY RAMP	4
31	3848 FAIRHAVEN DR	YES	UPHEAVAL NEAR CURB INLET ON WELLINGTON CT	4
32	3848 FAIRHAVEN DR	NO	SIDEWALK UPHEAVAL ON FAIRHAVEN	3
33	3844 FAIRHAVEN DR	YES	UPHEAVAL NEAR GREEN UTILITY BOX	4
34	3832 FAIRHAVEN DR	YES	UPHEAVAL AT SOUTH PROPERTY LINE	4
35	3832 FAIRHAVEN DR	YES	UPHEAVAL NEAR DRIVEWAY RAMP	3
36	3832 FAIRHAVEN DR	YES	UPHEAVAL NEAR NORTH PROPERTY LINE	5
37	3828 FAIRHAVEN DR	YES	UPHEAVAL NEAR STREET LIGHT	3
38	3822 FAIRHAVEN DR	NO	UPHEAVAL DUE TO ROOT FROM CHERRY TREE IN YARD	3
39	3818 FAIRHAVEN DR	YES	MAJOR UPHEAVAL	3
40	3825 FAIRHAVEN DR	YES	UPHEAVAL AT DRIVEWAY RAMP	2
41	3829 FAIRHAVEN DR	YES	UPHEAVAL NEAR DRIVEWAY RAMP	2
42	3837 FAIRHAVEN DR	YES	UPHEAVAL NEAR HANDICAP RAMP	2
43	3845 FAIRHAVEN DR	YES	2" UPHEAVAL	2
44	3865 FAIRHAVEN DR	YES	1" UPHEAVAL	2
45	3902 EDGEWOOD CT	YES	1" UPHEAVAL	2
46	3900 EDGEWOOD CT	YES	UPHEAVAL AT DRIVEWAY RAMP NEAR CURB INLET	2
47	3913 EDGEWOOD CT	YES	1" UPHEAVAL	2
48	2096 WELLINGTON DR	YES	1" UPHEAVAL	2
49	2080 WELLINGTON DR	YES	1" UPHEAVAL NEAR HYDRANT	2
50	2080 WELLINGTON DR	YES	2" UPHEAVAL	3
51	2070 WELLINGTON DR	YES	TWO 2" UPHEAVALS ONE EACH SIDE OF TREE	2
52	2030 WELLINGTON DR	YES	NEAR TREE AT DRIVEWAY RAMP	2
53	1810 RADCLIFFE CT	YES	PRIVATE STREET 2" UPHEAVAL AT DRIVEWAY RAMP	4
54	1835 RADCLIFFE CT	YES	PRIVATE STREET 1" UPHEAVAL NEAR TREE	4
55	4123 IMPERIAL DR	YES	1" UPHEAVAL	3
56	4103 IMPERIAL DR	YES	2-1/2" UPHEAVAL NEAR HYDRANT	3
57	4011 IMPERIAL DR	YES	1-1/2" UPHEAVAL	2
58	2941 BEACON HILL DR	YES	UPHEAVAL NEAR MAIL BOX	7
59	3590 RIVERKNOLL WAY	NO	BROKEN SIDEWALK NO TREE ISSUE	3
60	3590 RIVERKNOLL WAY	YES	BROKEN SIDEWALK NEAR TREE	5
61	3560 RIVERKNOLL WAY	YES	UPHEAVAL NEAR DRIVEWAY RAMP	3
62	3560 RIVERKNOLL WAY	YES	CRACKED SIDEWALK	4
63	3520 RIVERKNOLL WAY	YES	2" UPHEAVAL	3
64	3490 RIVERKNOLL WAY	YES	PROPERTY LINE WITH 3480 MINOR UPHEAVAL	2
65	3460 RIVERKNOLL WAY	YES	1" UPHEAVAL	3
66	3450 RIVERKNOLL WAY	YES	1" UPHEAVAL	3
67	3450 RIVERKNOLL WAY	YES	1-1/2" UPHEAVAL	3
68	3440 RIVERKNOLL WAY	YES	1/2" UPHEAVAL	5
69	3430 RIVERKNOLL WAY	YES	2" UPHEAVAL PREVIOUSLY GROUND	3
70	3420 RIVERKNOLL WAY	YES	2" UPHEAVAL	8
71	3350 BARRINGTON DR	NO	UPHEAVAL NEAR DRIVEWAY RAMP CAUSED BY BIRCH TREE IN YARD	3

72	3320 BARRINGTON DR	YES	UPHEAVAL NEAR PROPERTY LINE	6
73	3320 BARRINGTON DR	YES	UPHEAVAL	3
74	3300 BARRINGTON DR	YES	UPHEAVAL	3
75	3405 RIVERKNOLL WAY	YES	HANDICAP RAMP UPHEAVAL ABOVE CURB	2
76	3405 RIVERKNOLL WAY	YES	SIDEWALK CRACK	1
77	3405 RIVERKNOLL WAY	YES	UPHEAVAL	3
78	3405 RIVERKNOLL WAY	NO	SIDEWALK CRACK NEAR DRIVEWAY RAMP	1
79	3415 RIVERKNOLL WAY	YES	UPHEAVAL PREVIOUSLY REPAIRED STILL MOVING	2
80	3425 RIVERKNOLL WAY	YES	BROKEN AND LIFTED SIDEWALK NEAR DRIVEWAY RAMP AND TREE	1
81	3425 RIVERKNOLL WAY	YES	SIDEWALK CRACK	1
82	3425 RIVERKNOLL WAY	YES	1 PANEL SUNKEN ONE RAISED	2
83	3485 RIVERKNOLL WAY	YES	UPHEAVAL	1
84	2027 RIVERKNOLL CT	YES	UPHEAVAL	1
85	2037 RIVERKNOLL CT	YES	UPHEAVAL	3
86	2037 RIVERKNOLL CT	YES	UPHEAVAL	3
87	2037 RIVERKNOLL CT	YES	UPHEAVAL	2
88	2037 RIVERKNOLL CT	YES	CRACK BY TREE UPHEAVAL TO DRIVEWAY RAMP	2
89	2070 RIVERKNOLL CT	YES	UPHEAVAL	2
90	2010 RIVERKNOLL CT	YES	UPHEAVAL AT DRIVEWAY RAMP NEAR TREE	3
91	3565 RIVERKNOLL WAY	YES	UPHEAVAL AT DRIVEWAY RAMP NEAR TREE	2
92	3585 RIVERKNOLL WAY	YES	UPHEAVAL AT DRIVEWAY RAMP NEAR TREE	3
93	2871 BEACON HILL DR	NO	1 PANEL SUNKEN 1 PANEL RAISED NEAR WATER METERS CAUSED BY TREE IN YARD	2
94	2831 BEACON HILL DR	YES	UPHEAVAL AT TREE ROOTS HAVE BEEN CUT	3
95	2801 BEACON HILL DR	YES	SUNKEN PANEL NEAR HYDRANT AND TREE	1
96	3450 BARRINGTON DR	YES	UPHEAVAL WATER METERS TO DRIVEWAY RAMP	4
97	3450 BARRINGTON DR	YES	UPHEAVAL	4
98	3450 BARRINGTON DR	YES	UPHEAVAL DRIVEWAY RAMP TO STREET LIGHT	4
99	3410 BARRINGTON DR	YES	UPHEAVAL	2
100	3380 BARRINGTON DR	YES	UPHEAVAL AT DRIVEWAY RAMP PREVIOUSLY REPAIRED	1
101	3405 RIVERKNOLL WAY	YES	UPHEAVAL	1
<b>TOTAL PANELS =</b>				<b>280</b>